## **Asbestos Detections at the Border**

Data provided by Australian Border Force to the Asbestos and Silica Safety and Eradication Agency.

Data shown: July 2023 - June 2024

Data published: July 2024

Month	Number of asbestos tests at the border	Number of detections*	Asbestos types detected	Goods containing asbestos
Jun-24	46	1	1 x chrysotile asbestos	Motor vehicle
May-24	94	1	1 x chrysotile asbestos	Building products
Apr-24	47	3	3 x chrysotile asbestos	Building products
Mar-24	55	2	2 x chrysotile asbestos	Building products, Used motor vehicle and motor cycle
Feb-24	61	5	5 x chrysotile asbestos	Building products, Used motor vehicles, Pet incinerators
Jan-24	47	2	2 x chrysotile asbestos	Building products, Used motor vehicle parts
Dec-23	43	5	5 x Chrysotile Asbestos	Building products, Used motor vehicle parts
Nov-23	99	7	7 x Chrysotile Asbestos	Building products, Used motor vehicle parts
Oct-23	85	6	6 x Chrysotile Asbestos	Building products, Used motor vehicle parts
Sep-23	109	10	10 x Chrysotile Asbestos	Building products, Used motor vehicle parts, Hobby vehicle slipper clutch rebuild kits
Aug-23	102	6	6 x Chrysotile Asbestos	Construction materials, Used motor vehicle parts, packing material
Jul-23	94	5	5 x Chrysotile Asbestos	Motor vehicle parts

<sup>\*</sup> Multiple detections within one consignment or shipment is counted as <u>a single detection</u> within the statistics. Examples: a single consignment of multiple vehicles (including more than one detection in each vehicle) and/or vehicle parts, multiple gasket types or multiple slabs of cut stone.

Data published by the Asbestos and Silica Safety and Eradication Agency: Friday 12 July 2024.

Address: Level 4, 2 Constitution Avenue, Canberra, ACT 2601

Email: enquiries@asbestossafety.gov.au Website: www.asbestossafety.gov.au